

Windows XP Installation Guide

Installing EL-Skyport USB RX driver

Under [Windows XP](#), the Found New Hardware Wizard should be used to install devices when they are connected to the PC for the first time as this is the recommended procedure for reliable device operation.

To install drivers for EL-Skyport USB RX driver under Windows XP, follow the instructions below:

If a device of the same type has been installed on your machine before and the drivers that are about to be installed are different from those installed already, the original drivers need to be uninstalled. Please refer to the Uninstalling EL-Skyport USB RX driver section of this document for further details of this procedure.

If you are running Windows XP or Windows XP SP 1, temporarily disconnect your PC from the Internet. This can be done by either removing the network cable from your PC or by disabling your network card by going to the "Control Panel\Network and Dial-Up Connections", right clicking on the appropriate connection and selecting "Disable" from the menu. The connection can be re-enabled after the installation is complete. This is not necessary under Windows XP SP 2 if configured to ask before connecting to Windows Update. Windows XP SP 2 can have the settings for Windows Update changed through "Control Panel\System" then select the "Hardware" tab and click "Windows Update".

1. Connect the device to a spare USB port on your PC. This will launch the Windows Found New Hardware Wizard. If there is no available Internet connection or Windows XP SP 2 is configured to ask before connecting to Windows Update, the screen below is shown. Select "No, not this time" from the options available and then click "Next" to proceed with the installation. If there is an available Internet connection, Windows XP will silently connect to the Windows Update website and install any suitable driver it finds for the device in preference to the driver manually selected.
2. Select "Install from a list or specific location (Advanced)" as shown below and then click "Next".
3. Select "Search for the best driver in these locations" and enter the file path in the combo-box and browse to it by clicking the browse button and select the folder

[<CDROM drive>:\Windows\XP_2000_Server2003\](#)
or the downloaded Driver for WindowsXP, 2000 and Server 2003
[ELSkyport_USBRX_XP_2000_Server2003.zip](#)

Once the file path has been entered in the box, click next to proceed.

4. If Windows XP is configured to warn when unsigned (non-WHQL certified) drivers are about to be installed, a window will be displayed. Click on "Continue Anyway" to continue with the installation. If Windows XP is configured to ignore file signature warnings, no message will appear.
5. A window will be displayed as Windows XP copies the required driver files.
6. Windows should then display a message indicating that the installation was successful. Click "Finish" to complete the installation. This has installed the serial converter. The COM port emulation driver must be installed after this has completed.
7. After clicking "Finish", the Found New Hardware Wizard will continue by installing the COM port emulation driver. The procedure is the same as that above for installing the serial converter driver.

Uninstalling EL-Skyport USB RX driver

To uninstall EL-Skyport USB RX driver, follow the instructions below:

1. Disconnect any devices that are attached to the USB port of the PC.
2. Open the Add/Remove Programs utility located in "Control Panel\Add/Remove Programs". Select "ELINCHROM EL-Skyport USB RX driver" from the list of installed programs.
3. Click the "Add/Remove" button. This will run the FTDI uninstaller program. Click "Continue" to run the uninstaller or "Cancel" to exit.
4. When the uninstaller has finished removing the device from the system, the caption on the "Cancel" button will change to "Finish". Click "Finish" to complete the process.